



Affordable Computers & Technology for Tanzania

ACTT Hardware & Maintenance Pricing

Computer hardware:

Refurbished systems (includes CPU, keyboard, mouse and cables):

- Pentium III @ 996Mhz, 256Mb RAM, 20Gb = 190,000 Tsh
- Pentium III @ 996Mhz, 128Mb RAM, 20Gb = 170,000 Tsh
- Pentium III = 150,000 Tsh
- Pentium II = 130,000 Tsh
- Pentium I and pre-Pentium = 90,000 Tsh

Monitors (includes power cord):

- 21" monitor = 100,000 Tsh
- 17" monitor = 80,000 Tsh
- 15" monitor = 55,000 Tsh

Printers (includes adapter and power cord):

- Laser Jet = 150,000 Tsh
- Bubble Jet / Ink Jet (with ink) = 70,000 Tsh
- Bubble Jet / Ink Jet (without ink) = 50,000 Tsh

Peripherals (sold occasionally and as available):

- CDrom drive = 30,000 Tsh
- CD writer / DVD = 50,000 Tsh
- Ethernet router = 140,000 Tsh
- Floppy drive = 5,000 Tsh
- Hub (3-15 ports) = 20,000 Tsh
- Hub (16-24 ports) = 30,000 Tsh
- Keyboard = 8,000 Tsh
- Mouse = 3,000 Tsh
- Mouse pad = 1,000 Tsh
- Network card = 10,000 Tsh
- Power cable = 2,000 Tsh
- Printer cable = 3,000 Tsh
- RAM (128Mb) = 30,000 Tsh
- Scanner = 70,000 Tsh
- UPS (small) power stabiliser = 40,000 Tsh
- UPS (medium) power stabiliser = 80,000 Tsh

Maintenance & repair:

One year maintenance contracts are available for clients in Moshi and Arusha regions; contracts for clients outside these regions are determined according to distance and transport. Contracts include: 4 scheduled visits to the client sites for cleaning and software maintenance; 4 emergency visits if deemed necessary; and, parts replacement up to the value of one computer.

One year contract pricing for ACTT CTLCs:

- 5 to 9 computers = 198,000 Tsh
- 10 to 20 computers = 297,000 Tsh

One year contract pricing for other ACTT clients:

- 1 computer = 20,000 Tsh
- 5 to 9 computers = 418,000 Tsh
- 10 to 20 computers = 627,000 Tsh

Additional repair costs:

- Installation of new hardware = 5,000 Tsh
- Installation of operating system = 15,000 Tsh
- Installation of one application program = 10,000 Tsh

Important notes about pricing:

- Prices do not include technician's overnight accommodation (which costs additional 10,000 Tsh per technician).
- Clients will incur additional costs in the event that an ACTT monitor is broken.
- ACTT may terminate a contract if a recurring problem is caused by incompetence or lack of power protection devices.
- Parts are replaced after it is determined they cannot be fixed (a temporary replacement part is installed during repair).